ECS/EMD Configuration Change Request				Page 1 of Page(s)			e(s)		
1. Originator	2. Log Date:	3. CCR #:	4.	Rev:	5. Tel:	1	6. Rm #:	7. Org.	
Todd Edmands	5/19/04	04-0260		_	303-735-2418	:	376A	NSIDC	
8. CCR Title: Allow access to GUIs from outside production network.									
9. Originator Signature/Date			10. Class 1		11. Type:	. Type: 12. Need Date: 6/1/04		: 6/1/04	
Todd Edmands /s/ 5/17/04			II	CCR					
13. CCR Sponsor Signature/Date			14. Category o				"Emergency"		
Renea Ericson 5/17/04			Other	Other			fill in Block 27). Routine		
. ,			7. Schedul mpact:	dule 18. CI(s) Affected:					
19. Release Affected by this Change: 20. Date due			to Customer: 21. Estimated Cost:						
				None - Under 100K					
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:									
23. Problem: (use additional Sheets if necessary) NSIDC Operations and User Services groups need access to the GUIs which control subsystem configurations from the University's network.									
24. Proposed Solution: (use additional sheets if necessary) Create firewall rules which restirct access to the iplanet web servers which control ECS subsystems by the specific ip addresses of the desktop systems assigned to the University's operations and User Services' staff. The custom code and web server configurations will need to be mapped to a "u" interface to make them accessible from outside the production network.									
25. Alternate Solution: (use additional sheets if necessary)									
Use the proposed solution but require that the "Add Security Features to Synergy Operator GUIS" (OP_S4_01) be implemented which would require a password to be able to access the GUIs.									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)									
Groups which need access to the web servers must go to the operator's area and log onto an Xterminal connected to the production network in order to accomplish tasks for which they are responsible. NSIDC's operations' staff have responsibilities beyond ECS and simplifying access to the ECS GUIs will help them to work more efficiently.									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: DF PVC VATC EDC GSFC EDC IDG Test Cell Other				LaRC	aRC ⊠NSIDC □SMC □AK □JPL				
29. Board Comments:			;	30. W	Vork Assigned T	o: :	31. CCR C	losed Date:	
32. SCDV CCB Chair (Sign	/Date):	lienosition! A.	aproved A	nn/Ca	m Dicapproved	\ \ \ /:±	hdraw For	4/EGDIG EDD	
	7/04	Disposition: A		.pp/Co	m. ызарргоved	ı vvit	nuidw FW	d/ESDIS ERB	
33. EDF CCB Chair (Sign/D	late).		vd/ECS	nn/Cor	m Disannroyed	\//i+	hdraw Ewd	/FSDIS EDB	
Jo. LDI JOD GHAII (SIGH/D	B Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS								
34 ECS CCB Chair (Sign/D	lato):			n/Co~	n Disapproved	\ \ \ / i+	hdraw Eug	NEGDIG EDD	
34. EUS UUB Ullair (Sign/L	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERI								
Fwd/ESDIS									

CM01JA00 Revised 10/2/03 ECS/EDF/SCDV